North America Emission Control Area Fuel Oil Non-Availability Report
ECA0100
1 2 3
##

##(Include Double Pound for comments not form fields)
##Report Form ID Ship Operator Name Oldendorff Carriers PRT HOPE

4 5 6 7

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice PANAMA 9645566 30-Apr-13 OITA JAPAN

Name of Ports after First Notice Name of Last Port before ECA Entry VANCOUVER, BC, CANADA OITA, JAPAN Name of Port with Fuel Oil Supply Disruption OITA, JAPAN

11 12 13

 Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion 2200 LT 3.40% 48-72 hrs

Name of First POC Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC? **VANCOUVER, BC** Yes Yes

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

1+ n/a n/a

23 24

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC? n/a n/a

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months?

21-May-13 2400 LT N/A (VESSEL IS NEWLY BUILT)

Number of Separate Visits to the ECA Number of Ports visited in the ECA Previously submitted ECA0100 forms?

0 N/A

30

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail

Designated Corporate Official Phone Number

Description of Actions to Achieve Compliance

Owners unable to arrange Isfo prior departure shipyard.

Reasons: insufficient time and holiday in japan.

Vessel to continue using non compliant fuel oil until arrival 1st loadport where attempts to be made to supply co